The Ministry of Rural Development,

Rural Infrastructure Development for Cambodia Program (RID4CAM)

ICB: RID4CAM-W-SRP/BMC/OMC/BTB /Lot 19

ICB: RID4CAM-W-PVR/Lot 20

Circular 3

N°	Question	Answer
3	We would like to request for soft excel bill of quantities (BoQ) of bid document (ICB: RID4CAM-W- SRP/BMC/BTB/Lot 19 & RID4CAM-W-PVR/Lot 20)	The Employer <u>does not</u> make available the excel working files of the Bills of Quantities (BoQ).
		Please refer to the BoQs in PDF, as per the Bidding Documents and the BoQs in PDF made available with reference to ITB 7.1. [Clarification of Qualification and Bidding Documents, Site Visit, Pre-Bid Meeting] on the following web page: https://www.mrd.gov.kh/post-mrd-oct2025-001/
		In case of contradictions, the BOQs in PDF made available with reference to ITB 7.1. [Clarification of Qualification and Bidding Documents, Site Visit, Pre-Bid Meeting] prevail.
4	I am writing to request clarification regarding a discrepancy in the Bill of Quantities concerning flat-topped humps. Identified Discrepancy: The project documentation shows conflicting quantities for flat-topped humps: • Document 1: Shows 4 flat-topped humps (7m x 6.5m) - Item 10: Flat-topped Hump (Code M4-05) • Document 2: Shows 208.00 no. for item 1.12.7 "Flat-Topped Hump Marking" Request: Please clarify: 1. The correct quantity should be 4 flat-topped humps, not 208 2. Whether item 1.12.7 refers to road markings for the 4 humps or a separate item 3. Please provide a revised BOQ with consistent quantities This discrepancy affects cost estimation, procurement planning, and project deliverables.	The Employer makes available the corrected Bills of Quantities (BoQ) with reference to ITB 7.1. [Clarification of Qualification and Bidding Documents, Site Visit, Pre-Bid Meeting] on the following web page: https://www.mrd.gov.kh/post-mrd-oct2025-001/